

# SUPPLEMENT AIP URUGUAY

Telephone: 598 2604 0408 ext.  
5101, 5203  
Telefax: 598 2604 0067  
AFTN: SUMUYNXX  
e-mail: aispub@dinacia.gub.uy

ión Nacional de Aviación Civil e Infraestructura Aeronáutica  
Departamento AIS  
Aeropuerto Intl de Carrasco "Gral. Cesáreo L. Berisso"  
14000 Canelones

**AIP/SUP**  
**NR S 002**  
**15 DEC 2024**

---

## ATFM MEASURES

From 15 DEC 2024 00:01 UTC to 15 JAN 2025 23:59 UTC.

### ☛ 1 *Flight procedure towards Carrasco TMA for General Aviation*

☛ 1.1 General Aviation Aircrafts heading to Carrasco TMA via DORVO, shall have a 5-minute spacing between each other, unless otherwise coordinated between ATC units.

***Remember to register the inclusion of AIRAC amendment on page GEN 0.3-1  
Record of AIP Supplements***

